

Inspection Photos

API: 061-06234

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. There is some oily soils at red arrows that needs to be cleaned up.



Inspection Photos



Photo 2. View of oily soils found along the road..



Inspection Photos



Photo 3. Facing southeast toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 061-06234 | Date: 4/10/2024

Inspection Photos



Photo 4. Facing toward the onsite tank battery.

