

Inspection Photos

API: 061-06277

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2024

County: Prowers



Inspection Photos



Photo 1. Facing southeast toward the location.



Inspection Photos



Photo 2. The well has been cut and capped below grade and open excavation remains.



Inspection Photos



Photo 3. Facing south at the location all disturbance and bare areas will need to be reclaimed.



Inspection Photos



Photo 4. The open excavation should be protected to prevent livestock or wildlife entry.

