

Inspection Photos

API: 011-05059

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2024

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the location. Well sig is posted at meter shed.



Inspection Photos



Photo 2. Facing toward the TA'd well.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 011-05059 | Date: 4/10/2024

Inspection Photos



Photo 3. Facing toward the onsite tank which is fenced and a sufficient berm is constructed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API: 011-05059 | Date: 4/10/2024