

Inspection Photos

API: 011-05057

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2024

County: Prowers



Inspection Photos



Photo 1. Facing northeast toward the wellsite.



Inspection Photos



Photo 2. There is concrete debris and unused pipe that needs to be removed..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-05057 | Date: 4/10/2024

Inspection Photos



Photo 3. Northeast corner of the location. There is part of a metal shed and unused pipe that needs to be removed.



Inspection Photos



Photo 4. Facing northwest toward the wellsite.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 011-05057 | Date: 4/10/2024