

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 4/10/2024



Location Entrance – Photo #00516



Wellheads – Photo #00521

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 4/10/2024



Separators – Photo #00517



Tank Battery – Photo #00522

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 4/10/2024



Damaged Fencing – Photo #00519



Damaged Fencing – Photo #00520