

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403751038

Date Received:
04/11/2024

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>. General</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>
<u>Walker, Mandi</u>		<u>mwalker@hilcorp.com</u>
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000521
Inspection Date: 03/06/2024 FIR Submit Date: 03/08/2024 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 325510

Location Name: DAVIS GAS UNIT-N33N10W Number: 4NENW County: _____
Qtrqr: NENW Sec: 4 Twp: 33N Range: 10W Meridian: N
Latitude: 37.137327 Longitude: -107.943140

FACILITY - API Number: 05-067-00 Facility ID: 325510

Facility Name: DAVIS GAS UNIT-N33N10W Number: 4NENW
Qtrqr: NENW Sec: 4 Twp: 33N Range: 10W Meridian: N
Latitude: 37.137327 Longitude: -107.943140

CORRECTIVE ACTIONS:

1 CA# 192887

Corrective Action: Comply with rule 1002 Install or repair required BMPs. Date: _____

Response: CA COMPLETED Date of Completion: 04/11/2025

Operator Comment: Corrected on FIRR 714000145. Installed better material to bind large round rock. See attached photos

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Priscilla Shorty

Signed: _____

Title: OperationsRegulatory Tech

Date: 4/11/2024 1:29:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403751038	FIR RESOLUTION SUBMITTED
403751041	Davis Gas Unit 1_714000145 Resolved Photos

Total Attach: 2 Files