

Inspection Photos


Location Name: CHEVRON USA INC, SKINNER RIDGE-66S98W/28SESE

Location ID: 324351

Date: 4/11/2024



Location Entrance – Photo #00557



Wellhead – Photo #00561

Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE-66S98W/28SESE

Location ID: 324351

Date: 4/11/2024



Separator – Photo #00562



Tank Battery – Photo #00559

Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE-66S98W/28SESE

Location ID: 324351

Date: 4/11/2024



**Painted Label for Tank Content/Capacity/Operator Contact
Info is Weathered – Photo #00560**