

Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE 698-28-66S98W/28SESW

Location ID: 324266

Date: 4/11/2024



Location Entrance – Photo #00571



Wellhead – Photo #00566

Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE 698-28-66S98W/28SESW

Location ID: 324266

Date: 4/11/2024



Separator – Photo #00568



Tank Battery/Illegible Labeling on Tank – Photo #00565

Inspection Photos

Location Name: CHEVRON USA INC, SKINNER RIDGE 698-28-66S98W/28SESW

Location ID: 324266

Date: 4/11/2024



ECD – Photo #00567



Materials Handling/Spill Prevention – Photo #00569