

Inspection Photos

04/12/2023

Operator: VISION ENERGY LLC - 10770

Location ID: 322451

Inspection Doc: 696205746

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322451



Photo 1: Photos 1-3 taken from the Location. Photos examples showing that the Location does not meet 1004 requirements; Location bare, or vegetated predominantly by Undesirable Plant species.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322451



Photo 2: See comments under photo 1. Vegetation observed in photos predominantly Undesirable Plant Species such as *Melilotus officinalis*, and *Grindelia squarrosa*



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322451



Photo 3: See comments under photo 1. Vegetation observed in photos predominantly Undesirable Plant Species such as *Melilotus officinalis*, and *Grindelia squarrosa*



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322451



Photo 4: Photos examples of Noxious weeds (Common mullein, Musk thistle) observed on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources