

Inspection Photos
Location Name: N-Y Fletcher 14-26
API Number: 125-10526



1. Well sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: N-Y Fletcher 14-26
API Number: 125-10526



3. Chemical tank on secondary containment.



4. Well location overview.

Inspection Photos
Location Name: N-Y Fletcher 14-26
API Number: 125-10526



5. Well sign at production facility.



6. Vertical separator inside separator shed.

Inspection Photos
Location Name: N-Y Fletcher 14-26
API Number: 125-10526



7. Gas meter inside meter shed.



8. Produced water tank label. Peeling and faded needs to be replaced.

Inspection Photos
Location Name: N-Y Fletcher 14-26
API Number: 125-10526



9. Produced water flowing out of side of tank wall. Line has been broken off or removed.



10. Erosion channel from tank to pit.

Inspection Photos
Location Name: N-Y Fletcher 14-26
API Number: 125-10526



11. Pit overview.



12. Production facility location overview.