

# Final Reclamation and Stormwater Inspection

Date: 04/10/2024

Operator: VISTA OPERATING INC - 100128

Location ID: 317418

Inspection Document #: 708201137

Washington County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Longknife 22-31  
Location ID: 317418



**Photo 1.** Facing west near the former wellhead (red arrow). Photo illustrates subsidence and exposed soils.



Inspection Photos  
Location Name: Longknife 22-31  
Location ID: 317418



**Photo 2.** Continued from Photo 1; subsidence and exposed soils evident. Animal burrow indicated by red arrow.



Inspection Photos  
Location Name: Longknife 22-31  
Location ID: 317418



**Photo 3.** Facing north at the former pit. Non-uniform vegetation cover possibly a result of soil suitability or compaction issues.



Inspection Photos  
Location Name: Longknife 22-31  
Location ID: 317418



**Photo 4.** Facing west near the former pit; see comments in Photo 3.



Inspection Photos  
Location Name: Longknife 22-31  
Location ID: 317418



**Photo 5.** Taken near the northeast corner of the former pit; see comments in Photo 4.



Inspection Photos  
Location Name: Longknife 22-31  
Location ID: 317418



**Photo 6.** Adjacent reference area photo taken west of the former location.