

Final Reclamation and Stormwater Inspection

Date: 04/10/2024

Operator: VISTA OPERATING INC - 100128

Location ID: 317423

Inspection Document #: 708201138

Washington County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Longknife 14-30
Location ID: 317423



Photo 1. Taken near the eastern side of the former location. The former pit/production facilities do not appear to be progressing towards Rule 1004 with evidence of bare/exposed soils and no visible crop residue from last growing season to indicate uniform vegetation cover.

Inspection Photos
Location Name: Longknife 14-30
Location ID: 317423



Photo 2. Taken near the western side of the former location; see comments in Photo 1.

Inspection Photos
Location Name: Longknife 14-30
Location ID: 317423



Photo 3. Taken near the northern side of the former location; see comments in Photo 1.

Inspection Photos
Location Name: Longknife 14-30
Location ID: 317423



Photo 4. Taken near the southern side of the former location; see comments in Photo 1.

Inspection Photos
Location Name: Longknife 14-30
Location ID: 317423



Photo 5. Former wellhead location (green arrow) appears to be progressing towards reclamation standards with evidence of crop residue. Additional reclamation activities are required at the former production facilities/pit, indicated by red arrow in the background.