

Inspection Photos

Facility Name: Siebring Pad/5-63-32-16H

Facility ID: 430337



Photo #1

Siebring Pad/5-63-32-16H North Pad Battery site
Inactive | Shut-down



Photo #2

Siebring Pad/5-63-32-16H North Pad Battery site
Inactive | Shut-down
Battery entrance



Inspection Photos

Facility Name: Siebring Pad/5-63-32-16H

Facility ID: 430337



Photo #3

Siebring Pad/5-63-32-16H North Pad Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #4

Siebring Pad/5-63-32-16H North Pad Battery site

Inactive | Shut-down

ECD(s), Separator(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Facility Name: Siebring Pad/5-63-32-16H
Facility ID: 430337



Photo #5

Siebring Pad/5-63-32-16H North Pad Battery site

Inactive | Shut-down

Facility / Battery sign



Photo #6

Siebring/5-63-32 North Pad

Wellsite(s): 4

Shut-In | SI

N → S



Inspection Photos

Facility Name: Siebring Pad/5-63-32-16H

Facility ID: 430337

Associated Wells	API	Status
1. Siebring 5-63-32-16H	123-35268	SI
2. Siebring 5-63-32-17H	123-35261	SI
3. Siebring 5-63-32-32H	123-35260	SI
4. Siebring 5-63-32-48H	123-35263	SI

Photo #11

Siebring Pad/5-63-32-16H North Pad Battery site

Inactive | Shut-down

Associated well(s)

4: Shut-In | SI

N → S



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources