


Inspection Photos
Location Name: Jones 2
API Number: 125-07102



1. Well sign on meter shed at location.



2. View of wellhead.

Inspection Photos
Location Name: Jones 2
API Number: 125-07102



3. Vertical separator and gas meter inside shed.



4. Produced water tank.

Inspection Photos
Location Name: Jones 2
API Number: 125-07102



5. Soil erosion around meter shed.



6. Erosion channel heading down grader from meter shed.

Inspection Photos
Location Name: Jones 2
API Number: 125-07102



7. Erosion cut from meter shed and produced water tank.



8. Erosion channel looking up the grade towards produced water tank.

Inspection Photos
Location Name: Jones 2
API Number: 125-07102



9. Erosion channels coming off location through fencing.



10. Location overview.