

Inspection Photos

API: 071-08232

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/15/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. The culverts are maintained along the road.



Inspection Photos



Photo 2. Facing southeast toward the wellsite.



Inspection Photos



Photo 3. The electric panel has been repaired.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. There is still oil stained soil by the engine skid and oil in the skid that needs to be cleaned up better.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources