

# Inspection Photos

April 12th, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 333343

Inspection Document #: 714000674

Archuleta County, CO

Township: SESW 14 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343



4/12/24  
+37.013387,-107.469961  
323° NW



**Photo 1.** View of the well disturbance from the access point facing center.



Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 2.** View of weedy kochia/russian thistle weedy debris dominating produced water tank/berm area.

API #: 007-06201



Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343



4/12/24  
+37.013538,-107.470720  
339° N

**Photo 3.** View of western interim reclamation area facing north.  
Vegetation comprised of rabbit brush.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 007-06201



Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343



**Photo 4.** Wildlife netting covering plastic secondary containment at pump jack is no longer functioning, maintenance is required.





Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343



**Photo 5.** View of impacted surface material at 14-2 pump jack.





Inspection Photos  
Location Name: Peterson 32-6 14-2, 4  
Location ID: 333343

4/12/24  
+37.013538,-107.470720  
306° NW



**Photo 6.** Reference area comprised of rabbitbrush and smooth brome.

