

Inspection Photos

April 12th, 2024

Operator: Logos Operating LLC - 10679

Location ID: 307022

Inspection Document #: 714000683

La Plata County, CO

Township: SWSE 16 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Espinosa 1A
Location ID: 307022



4/12/24
+37.012562,-107.503689
315° NW



4/12/24
+37.012764,-107.503920
333° NW

LOGOS OPERATING, LLC.

ESPINOSA #001A MV
FEE
API NO. 05-067-09595
990' FSL & 2403' FEL
SEC.16 T32N R06W NMPM
LA PLATA COUNTY, CO
LAT: 37.01572 LONG: 107.51075
EMERGENCY CONTACT # 1-866-598-6220
OR 911

Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Espinosa 1A
Location ID: 307022

4/12/24
+37.012730,-107.504056
310° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of western cut slope/interim reclamation area that remains unstabilized. Bare soils need erosion controls until stabilized with desirable perennial vegetation.

API #: 067-09595

Inspection Photos
Location Name: Espinosa 1A
Location ID: 307022



4/12/24
+37.012639,-107.503960
143° SE

Photo 3. Plastic and barbed wire fence debris observed in the western edge of the disturbance.

Inspection Photos
Location Name: Espinosa 1A
Location ID: 307022



Photo 4. View of weedy russian thistle debris in the center of the disturbance.

Inspection Photos
Location Name: Espinosa 1A
Location ID: 307022

