

Inspection Photos

04/12/2023

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053

Inspection Doc: 696205752

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north. Photos also show all production equipment Located on the eastern half of the Location; western half of the working pad surface is no longer necessary for production, and requires reclamation pursuant to Rule 1003.b.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 3: Photos 3-4 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west. Photos also show all production equipment Located on the eastern half of the Location; western half of the working pad surface is no longer necessary for production, and requires reclamation pursuant to Rule 1003.b.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 5: 2023 Google earth imagery. Red polygon represent approximate areas of the Location requiring reclamation pursuant to Rule 1003.b.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 6: Photo shows the single PR well remaining on Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 7: Photos 7-8 taken from the southern end of the tank battery facility. Photos examples showing holes within the secondary containment measure; BMP is no longer sufficiently impervious to contain a spill or release.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335053



Photo 8: See comments under photo 7.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources