

Inspection Photos

API: 055-06314

Operator: OXY USA INC

Inspection Date: 4/16/2024

County: HUERFANO



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest toward the wellsite.



Inspection Photos



Photo 2. There is an oily sheen in the water at the well cellar.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing west at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing northeast along the fill slope.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources