

Caerus Piceance LLC  
Piceance Creek Unit T57X-19G  
Location ID: 316254



**Information missing and illegible information.**

**When replaced additional information will be required**

Caerus Piceance LLC  
Piceance Creek Unit T57X-19G  
Location ID: 316254



Missing tank battery sign



Load line plug?

**Caerus Piceance LLC  
Piceance Creek Unit T57X-19G  
Location ID: 316254**



**Location from Southwest corner**

**Location from Southeast corner**

Caerus Piceance LLC  
Piceance Creek Unit T57X-19G  
Location ID: 316254



Location from Northeast corner



Location from Northwest corner