

Interim Reclamation and Stormwater Inspection

April 11, 2024

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 460656

Inspection Document #: 697505258

Weld County, CO

NWNE Section 28 T1N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ROY SWD FACILITY
Location ID: 460656



Photo 1. Photo taken from the entrance of location, facing South. Photo illustrates the Operator sign. Also, photo illustrates vehicle traffic within the interim reclamation area, damaging reclamation.



Inspection Photos
Location Name: ROY SWD FACILITY
Location ID: 460656



Photo 2. Photo taken from the topsoil stockpile, facing East. Photo illustrates the Operator has performed interim reclamation activities.

Operator did not stabilize the seeded soil per the previous corrective action.



Photo 3. Photo taken from the topsoil stockpile, facing West. See comments under Photo 2.

Inspection Photos
Location Name: ROY SWD FACILITY
Location ID: 460656



Photo 4. Photo taken from the topsoil stockpile, facing South.
See comments under Photo 2.



Photo 5. Photo taken from the topsoil stockpile, facing North.
See comments under Photo 2.