

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102




Photo 1 – West Wellheads

Photo 2 – 2029-01H Wellhead

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 3 – East Wellheads

Photo 4 – 2021-01H Wellhead

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 5 – Separator, Instrumental Air Unit and ECDs

Photo 6 – Well Headers

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 7 – Compressor

Photo 8 – Unused Building Materials in NE Corner

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 9 – Separators



Photo 10 – Separator and ECDs

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 11 – VRT and Tanks

Photo 12 – Tank Battery Signs

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 13 – LACT

Photo 14 – VRU

Inspection Photos
Location Name: Bringleson Federal 2021-2029 PAD
Location ID: 467102



Photo 15 – Unmarked Risers at VRU

Photo 16 – Unmarked Risers at VRU