

## Inspection Photos

Location Name: Bringleson Ranch 20-11-9-58 PAD

Location ID: 423722



Energy and Carbon Management Commission  
40.74071, -103.8962, 4770.1ft  
04/15/2024 13:16:44

**Photo 1 – Gas Meter House and ECD**



Energy and Carbon Management Commission  
40.74066, -103.89627, 4789.1ft  
04/15/2024 13:16:50

**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Bringleson Ranch 20-11-9-58 PAD**  
**Location ID: 423722**



**Photo 3 – Tank Battery Sign**



**Photo 4 – Heater Treaters and Propane Tank**



## Inspection Photos

Location Name: Bringleson Ranch 20-11-9-58 PAD

Location ID: 423722



**Photo 5 – Tank Battery**



**Photo 6 – Unused Secondary Containment in SE Corner**

## Inspection Photos

Location Name: Bringleson Ranch 20-11-9-58 PAD

Location ID: 423722



**Photo 7 – Pumping Units**



**Photo 8 – Unused Rods and Tubing**



## Inspection Photos

Location Name: Bringleson Ranch 20-11-9-58 PAD

Location ID: 423722



Photo 9 – Sign at Entrance