

Final Reclamation and Stormwater Inspection

Date: 04/17/2024

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - 8960

Location ID: 306270

Inspection Document #: 708201161

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: State Pronghorn 11-16
Location ID: 306270



Photo 1. Access road has not been recontoured/graded to reflect adjacent topography.

Inspection Photos
Location Name: State Pronghorn 11-16
Location ID: 306270



Photo 2. Access road has not been recontoured/graded to reflect adjacent topography.

Inspection Photos
Location Name: State Pronghorn 11-16
Location ID: 306270



Photo 3. The former tank battery location (southern/southwestern portion) has not been recontoured/graded to reflect adjacent topography.

Inspection Photos
Location Name: State Pronghorn 11-16
Location ID: 306270



Photo 4. The former tank battery location (southern/southwestern portion) does not appear to have uniform vegetation cover of desirable species.

Inspection Photos
Location Name: State Pronghorn 11-16
Location ID: 306270



Photo 5. Continued from Photo 4, facing southeast.

Inspection Photos
Location Name: State Pronghorn 11-16
Location ID: 306270



Photo 6. Road base and gravel remain throughout the southern portion of the location.