

## Inspection Photos

Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4

Location ID: 332754



Photo 1: Wellhead sign



Photo 2: Wellhead





## Inspection Photos

Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4

Location ID: 332754



Photo 3: Incorrect Wellhead sign

Photo 4: Wellhead



## Inspection Photos

Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4

Location ID: 332754



Energy & Carbon Management Commission  
40.24912, -104.67087, 1437.4m, 15°  
Apr 18, 2024 10:54:50



Energy & Carbon Management Commission  
40.24924, -104.67076, 1451.0m, 14°  
Apr 18, 2024 10:55:04

Photo 5: Wellhead Sign

Photo 6: Wellhead



**Inspection Photos**  
**Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4**  
**Location ID: 332754**



**Energy & Carbon Management Commission**  
40.24919, -104.66979, 1450.5m, 18°  
Apr 18, 2024 11:01:46



**Energy & Carbon Management Commission**  
40.24914, -104.66978, 1451.5m, 11°  
Apr 18, 2024 11:02:24

**Photo 7: Tank Battery Signs**

**Photo 8: Centralized tank battery**



## Inspection Photos

Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4

Location ID: 332754



Photo 9: Contents is not legible



Photo 10: Contents/capacity is not legible.

## Inspection Photos

Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4

Location ID: 332754



Photo 11: Debris



Photo 12: Debris



## Inspection Photos

Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4

Location ID: 332754



Photo 13: Debris



Photo 14: Debris/unused equipment



## Inspection Photos

Location Name: Aristocrat Angus 4-8-4, 1-6-4, 3-6-4

Location ID: 332754



Photo 15: Debris/unused equipment



Photo 16: Debris