

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



When replaced additional information is required



Equipment leak

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Erosion and sediment migration



Erosion and sediment migration

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Erosion and sediment migration

Erosion and sediment migration

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Erosion and sediment migration

Erosion and sediment migration

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Incomplete cleanup of previous spill



Oil spill cleanup incomplete. Cattle in the area.

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Metal berm seepage



Oil spill cleanup incomplete. Cattle in the area.

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Oil spill cleanup incomplete. Cattle in the area.



Metal berm leakage

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Oil spill cleanup incomplete. Cattle in the area.

Oil spill cleanup incomplete. Cattle in the area.

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Stained soil outside of berm



Well sign missing required information

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Sediment migration




Sediment migration

KT Resources LLC
 WRD Federal 19-31
 Location ID: 316279



Unused equipment storage



Gas calibration out of date

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Location from Northwest corner



Location from Northeast corner

**KT Resources LLC
WRD Federal 19-31
Location ID: 316279**



Location from Southeast corner



Location from Southwest corner