


KT Resources LLC
 Ant Hill Unit 29-11
 Location ID: 316309



Gas calibration out of date

Well sign missing required information

**KT Resources LLC
Ant Hill Unit 29-11
Location ID: 316309**



Unused equipment storage



Stained soil from equipment leak

**KT Resources LLC
Ant Hill Unit 29-11
Location ID: 316309**



Disturbed gravel covering stained soil



Disturbed gravel covering stained soil

**KT Resources LLC
Ant Hill Unit 29-11
Location ID: 316309**



Location from Northeast corner



Location from Northwest corner

**KT Resources LLC
Ant Hill Unit 29-11
Location ID: 316309**



Location from Southwest corner



Location from Southeast corner