

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403729865
Receive Date:
03/25/2024
Report taken by:
Jason Kosola

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: ENDURING RESOURCES LLC Operator No: 10663 Phone Numbers
Address: 6300 S SYRACUSE WAY, SUITE 525 Phone: (720) 768-3575
City: CENTENNIAL State: CO Zip: 80111 Mobile: (720) 768-3575
Contact Person: Kayla White Email: kwhite@cdhconsult.com

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 34556 Initial Form 27 Document #: 403664009

PURPOSE INFORMATION

- [X] Rule 913.c.(1): Pit or Cuttings Trench closure.
- [] Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- [] Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- [] Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- [] Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- [] Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- [] Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- [] Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- [] Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- [] Rule 913.g: Changes of Operator.
- [] Rule 915.b: Request to leave elevated inorganics in situ.
- [] Other:

SITE INFORMATION

No Multiple Facilities

Facility Type: PIT Facility ID: 115981 API #: County Name: LA PLATA
Facility Name: SAM BURCH 8 Latitude: 37.047790 Longitude: -107.806226
** correct Lat/Long if needed: Latitude: Longitude:
QtrQtr: SENE Sec: 3 Twp: 32N Range: 9W Meridian: N Sensitive Area? Yes

SITE CONDITIONS

General soil type - USCS Classifications SP Most Sensitive Adjacent Land Use commercial
Is domestic water well within 1/4 mile? Yes Is surface water within 1/4 mile? Yes
Is groundwater less than 20 feet below ground surface? Yes

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input checked="" type="checkbox"/> Non-E&P Waste |
| <input type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | We believe this pit was never constructed
_____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
No	SOILS	none	Review of drone imagery

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

In August 2023 Enduring Resources, LLC (Enduring) and CDH Consulting, LLC, (CDH), conducted a thorough desktop analysis of all identified Enduring owned pits not closed in the ECMC database. These pit locations were historic locations that were permitted before Enduring Resources took ownership of the assets in the area. The Sam Burch 8 pit location was originally permitted by the Texaco Oil Company in 1977 and was reclaimed before Enduring took ownership in 2017. However proper closure documentation was not submitted to ECMC by the prior operator and the record remains open in the ECMC database. This Form 27 serves as a closure request for the Sam Burch 8 pit location, ECMC location ID: 115981. During the desktop analysis, CDH reviewed operating documents from Enduring, reviewed historically filed document on the ECMC database, and viewed historic imagery from available resources including Google Earth and recently collected drone data to determine the presence or absence of previously permitted pits. For the Sam Burch 8 pit location, it was determined based on the desktop review that a pit likely never existed.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 0
Number of soil samples exceeding 915-1 _____
Was the areal and vertical extent of soil contamination delineated? Yes
Approximate areal extent (square feet) 0

NA / ND

_____ Highest concentration of TPH (mg/kg) _____
_____ Highest concentration of SAR _____
_____ BTEX > 915-1 _____
_____ Vertical Extent > 915-1 (in feet) _____

Groundwater

Number of groundwater samples collected 0
Was extent of groundwater contaminated delineated? No
Depth to groundwater (below ground surface, in feet) _____
Number of groundwater monitoring wells installed _____
Number of groundwater samples exceeding 915-1 _____

_____ Highest concentration of Benzene (µg/l) _____
_____ Highest concentration of Toluene (µg/l) _____
_____ Highest concentration of Ethylbenzene (µg/l) _____
_____ Highest concentration of Xylene (µg/l) _____
_____ Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected
_____ Number of surface water samples exceeding 915-1
If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____ Volume of liquid waste (barrels) _____

Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Please see the attached drone imagery collected on April 17, 2023 for reference. No pit exists and we do not believe a pit was ever constructed.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

CDH conducted a thorough review of the ECMC database along with securing drone imagery and determined that a pit likely never existed. Please see the included attachments for reference and support of our position.

Soil Remediation Summary

In Situ

- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Air sparge / Soil vapor extraction
- Natural Attenuation
- Other _____

Ex Situ

- Excavate and offsite disposal
- If Yes: Estimated Volume (Cubic Yards) _____
- Name of Licensed Disposal Facility or ECMC Facility ID # _____
- Excavate and onsite remediation
- Land Treatment
- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Other _____

Groundwater Remediation Summary

- Bioremediation (or enhanced bioremediation)
- Chemical oxidation
- Air sparge / Soil vapor extraction
- Natural Attenuation
- Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

Quarterly Semi-Annually Annually Other

Request Alternative Reporting Schedule:

Semi-Annually Annually Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type: Groundwater Monitoring Land Treatment Progress Report O&M Report
 Other NONE

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

Operator anticipates the remaining cost for this project to be: \$

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

ECMC Disposal Facility ID #, if applicable:

Non-ECMC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? Yes

If YES:

Compliant with Rule 913.h.(1).

Compliant with Rule 913.h.(2).

Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards? Yes

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards? Yes

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Please see the attached drone imagery collected on April 17, 2023 for reference. No pit exists and we do not believe a pit was ever constructed.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/17/2023

Proposed site investigation commencement. 04/17/2023

Proposed completion of site investigation. 04/17/2023

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

The approved initial Form 27 (DOC # 403664009) indicates the ECMC database was searched and a review of records and historic aerial photos shows no evidence of this pit ever being constructed. Enduring Resources respectfully requests that this record be closed administratively with no subsequent reporting being required.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Danielle Gavito

Title: Senior Regulatory Analyst

Submit Date: 03/25/2024

Email: dgavito@cdhconsult.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Jason Kosola

Date: 04/22/2024

Remediation Project Number: 34556

COA Type**Description**

	<p>NO FURTHER ACTION Based on the information presented, it appears that no further action is necessary at this time and the ECMC approves the closure request. However, if future conditions at the site indicate contaminant concentrations in soils exceeding ECMC standards or if groundwater is found to be impacted, then further investigation and/or remediation activities may be required.</p> <p>The surface area disturbed by the remediation activity shall be reclaimed in accordance with the 1000 Series Reclamation Rules. For locations with active ongoing oil and gas operations, comply with Rule 1003 interim reclamation requirements and for locations that will no longer have active oil and gas operations, comply with Rule 1004 Final Reclamation requirements.</p>
1 COA	

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

<u>Att Doc Num</u>	<u>Name</u>
403729865	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
403730127	OTHER
403763386	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)