

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 4569 From entrance to location



Photo # 4570 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 4571 Location



Photo # 4572 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 4573 Location



Photo # 4574 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 987 From inspection 708903378 conducted on 03/21/2024 Methanol tank improperly labeled/lacks required information



Photo # 4575 Methanol tank improperly labeled/lacks required information

Inspection Photos

Location Name: CAERUS PICEANCE LLC SAVAGE 1-13 (RB1) Pad

Location #: 334637



Photo # 988 From inspection 708903378 conducted on 03/21/2024 Methanol tank improperly labeled/lacks required information



Photo # 4576 Methanol tank improperly labeled/lacks required information