

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2024

Submitted Date:

04/22/2024

Document Number:

708903601

FIELD INSPECTION FORMLoc ID 335804 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

32 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276472	WELL	PR	12/19/2006	GW	045-10474	N.PARACHUTE EF02B A28 595	PR
276473	WELL	SI	10/01/2023	GW	045-10475	N. PARACHUTE EF07B A28 595	SI
276474	WELL	PR	04/18/2006	GW	045-10476	N.PARACHUTE EF08B A28 595	PR
277383	WELL	PR	04/21/2006	GW	045-10697	N. PARACHUTE EF07D A28 595	PR
277384	WELL	PR	04/02/2006	GW	045-10698	N. PARACHUTE EF01B A28 595	PR
277385	WELL	PR	04/21/2006	GW	045-10699	N. PARACHUTE EF15D A28 595	PR
277435	WELL	PR	05/31/2007	GW	045-10702	N. PARACHUTE EF02D A28 595	PR
277436	WELL	PR	05/22/2007	GW	045-10703	N. PARACHUTE EF15B A28 595	PR

General Comment:

CECMC Inspection Report Summary

On 04/22/2024 at approximately 14:30 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at CAERUS PICEANCE LLC N.PARACHUTE EF07B A28 595 Pad.

Location # 335804 in Garfield County Colorado.

Please refer to inspection 708903306 conducted on 03/14/2024, previous corrective action has been completed.

Location is within High Priority/Density/NSO/Black Bear Habitat areas.

Location is approximately 86 yards from East Fork Parachute Creek.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Unmarked deadman with a CA date of 05/06/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Production separation equipment & tank battery located at Middlefork Station facility #'s 419757 & 470699

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No tank battery on location		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	1 Chemical tank - Jersey barriers 1 Chemical tank - Jersey barriers & pipe rail fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Jersey barriers		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sales meter houses - pipe rail fence		
Corrective Action:		Date:	

Type	OTHER		
Comment:	Gas lift meter houses - jersey barriers		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Test separator - pipe rail fence		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	Test separator		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	1 unmarked deadman		
Corrective Action:	All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor.	Date:	05/06/2024
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Sales		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Thermoelectric generator		
Corrective Action:		Date:	
Type: Gas Meter Run	# 8		
Comment:	Gas lift		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 276472 Type: WELL API Number: 045-10474 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut In

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276473 Type: WELL API Number: 045-10475 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut In

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 276474 Type: WELL API Number: 045-10476 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut In

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277383 Type: WELL API Number: 045-10697 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut In

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277384 Type: WELL API Number: 045-10698 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut In

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 277385 Type: WELL API Number: 045-10699 Status: PR Insp. Status: PR

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: Shut In

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	277435	Type:	WELL	API Number:	045-10702	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle Well	
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____
Comment:	<input type="text" value="Shut In"/>
Corrective Action:	<input type="text"/> Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	277436	Type:	WELL	API Number:	045-10703	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Idle Well	
Purpose:	<input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____
Comment:	<input type="text" value="Shut In"/>
Corrective Action:	<input type="text"/> Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in small areas
		Ditches				
		Compaction				
				Material Handling And Spill Prevention		Chemical tank containments
		Culverts				
Compaction						Light compaction in some areas
Berms						
		Gravel				Sparse to none

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	278620	1433001	
	278620	1433001	

ECMC Comments

Comment	User	Date
Please refer to Equipment for observed compliance issue	smelserw	04/22/2024
Production separation equipment & tank battery located at Middlefork Station facility #'s 419757 & 470699		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903602	Inspection 708903601 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520023
708903603	Inspection 708903601 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6520024