

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 4/18/2024



Wellheads – Photo #00713



Separators – Photo #00717

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 4/18/2024



Tank Battery – Photo #00718



Weathered Wellhead Sign – Photo #00714

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 4/18/2024



Weathered Wellhead Sign – Photo #00715



Weathered Wellhead Sign – Photo #00716

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/29SENE

Location ID: 335328

Date: 4/18/2024



Weathered Battery Sign – Photo #00719