

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28NWSW

Location ID: 335352

Date: 4/18/2024



Wellheads – Photo #00721



Separators – Photo #00726

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28NWSW

Location ID: 335352

Date: 4/18/2024



Tank Battery – Photo #00725


Weathered Wellhead Sign – Photo #00722

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/28NWSW

Location ID: 335352

Date: 4/18/2024



Weathered Wellhead Sign – Photo #00723

Weathered Wellhead Sign – Photo #00724