

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4648 From entrance to location



Photo # 4649 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4650 Location



Photo # 4651 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4652 Location



Photo # 4653 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4654 Location



Photo # 4655 Open hole/wildlife & personnel hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4656 Open ended piping/wildlife hazard



Photo # 4657 Open ended piping/wildlife hazard

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4658 Stained soils & gravel



Photo # 4659 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4660 Stained soils & gravel



Photo # 4661 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4662 Stained soils & gravel



Photo # 4663 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4664 Stained soils & gravel



Photo # 4665 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4666 Stained soils & gravel



Photo # 4667 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4668 Stained soils & gravel



Photo # 4669 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4670 Stained soils & gravel



Photo # 4671 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4672 Stained soils & gravel



Photo # 4673 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4674 Stained soils & gravel



Photo # 4675 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC N. PARACHUTE H29A 595 Pad

Location #: 335594



Photo # 4676 Stained soils & gravel



Photo # 4677 Stained soils & gravel