

**Operator:** *HIGHPOINT OPERATING CORPORATION*

**Location Name:** *Coffelt 5-61-35\_36 NWNW*

**Loc ID:** *439471*

**Inspection:** *708201153*



Exhibit A



Exhibit B





Exhibit C



Exhibit D





Exhibit E



Exhibit F





Exhibit G





Exhibit H



Exhibit I





Exhibit J

**CA:** *Stained soils were observed both inside and outside of secondary containment at tank battery and near equipment. Properly dispose of oily waste in accordance with Rule 905.e.*

**CA Resolution:** *Oily waste has been properly disposed of in accordance with Rule 905.e.*

**CA:** *Tumbleweed accumulations were observed throughout the location and within equipment. Comply with Rule 606 to remove weed debris.*

**CA Resolution:** *Tumbleweeds have been removed to comply with Rule 606.*

**CA:** *Trash and debris observed throughout the location. Comply with Rule 606 and remove all trash/debris from the location.*

**CA Resolution:** *Trash and debris has been removed to comply with Rule 606.*