

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/11/2024

Submitted Date:

04/24/2024

Document Number:

714300058

FIELD INSPECTION FORM

 Loc ID 440427 Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-
Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486442	SPILL OR RELEASE	CL	04/05/2024		-	Hunziker 28N-28HZ Wellhead	EI

General Comment:

This is an environmental inspection to determine progress on Spill ID 486442/Remediation Project No 31664. Any corrective actions from previous inspections that have not been addressed are still applicable.

There were no operator or contract environmental personnel on location at the time of this field inspection.

Photos attached to document site conditions.

Inspected Facilities

Facility ID: 486442 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Remediation excavation is open. Water was observed within the excavation. No sheen was observed on the water.

Corrective Action: Operator shall provide an updated Form 27 for Remediation #31664 with a workplan and timeline for remediation of Spill ID 486442. Date: 05/01/2024

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
Comment	An unlined soil stockpile remains on location surrounded by berms. No indication if the stockpile is contaminated.				
Corrective Action	If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to remediation closure.				Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714300059	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6522366