

**Operator:** *Bonanza Creek Energy*  
**Location Name:** *Pronghorn D-28 Pad*  
**Loc ID:** *441005*  
**Inspection:** *708201158*



Exhibit A



**Exhibit B**

**CA:** *Tumbleweed accumulations observed throughout the location and within equipment. Degraded straw wattles at SE sediment trap need to be removed as they are not intact. Comply with Rule 606 and remove all debris on location.*

**CA Resolution:** *Debris has been removed to comply with Rule 606.*