

Inspection Photos

April 23rd, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 424696

Inspection Document #: 714000702

Archuleta County, CO

Township: NWNE 20 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Navajo Lake 32-5 21-2, 1
Location ID: 424696

4/23/24
+37.009651,-107.414950
4° N



4/23/24
+37.010111,-107.414496
25° NE



4/23/24
+37.009979,-107.415059
31° NE

Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos

Location Name: Navajo Lake 32-5 21-2, 1

Location ID: 424696



Photo 2. View of weedy russian thistle debris piling up in the northwest and northeast corner of the disturbance.

Inspection Photos

Location Name: Navajo Lake 32-5 21-2, 1

Location ID: 424696



Photo 3. View of unused plastic secondary containment observed on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06308, 06309

Inspection Photos
Location Name: Navajo Lake 32-5 21-2, 1
Location ID: 424696

4/23/24
+37.010004,-107.414095
203° SW



Photo 5. View of additional weedy russian thistle debris lining the southern fence line of the disturbance.

Inspection Photos

Location Name: Navajo Lake 32-5 21-2, 1

Location ID: 424696



Photo 6. View of russian olive tree that remains in the southern interim reclamation area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06308, 06309