

Inspection Photos

API: 071-07584

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 4/24/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing northeast along the access road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. At the switchback of the road there is sediment accumulation that has filled in the rip/tap outlet. This BMP will need to be repaired and additional BMP's should be installed further up the road to prevent erosion.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing south along the road. The remainder of the road is stabilizing well with vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



April 24, 2024
+37.089027, -104.827364

Photo 5. Facing northeast along the road. The remainder of the road is stabilizing well with vegetation.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing east toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. Facing east at the location. There are some areas with less vegetation most of which was non-native Smooth brome and Alfalfa .



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 8. Facing south at the location.



Inspection Photos



Photo 9. Facing southeast at the location. Some areas of the location are progressing more.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources