

Inspection Photos

April 23rd, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 320879

Inspection Document #: 714000718

Archuleta County, CO

Township: NESE 18 32N 5W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Hauschild 32-5 18-2
Location ID: 320879

4/23/24
+37.015637,-107.428455
167° S



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Hauschild 32-5 18-2
Location ID: 320879



Photo 2. Weedy debris observed at the tank berm.

Inspection Photos
Location Name: Hauschild 32-5 18-2
Location ID: 320879



Photo 3. Rutting observed on location, additional stabilization is needed to minimize site degradation.

Inspection Photos

Location Name: Hauschild 32-5 18-2

Location ID: 320879




Photo 4. View of erosion forming on the southern edge of the disturbance.

4/23/24
+37.015115,-107.428133
4° N



Photo 5. View of the northern interim reclamation area comprised of rabbit brush.

Inspection Photos
Location Name: Hauschild 32-5 18-2
Location ID: 320879



Photo 6. Reference area comprised of juniper and under story of grazed grasses.