

Inspection Photos

April 23rd, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 334036

Inspection Document #: 714000719

Archuleta County, CO

Township: NENE 13 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Schumacher 32-6 13-1, 2
Location ID: 334036

4/23/24
+37.021988,-107.444795
235° SW



Photo 1. View of the disturbance taken from the access point facing center.

Inspection Photos
Location Name: Schumacher 32-6 13-1, 2
Location ID: 334036



Photo 2. Weedy debris observed at the tank berm.

Inspection Photos
Location Name: Schumacher 32-6 13-1, 2
Location ID: 334036



Photo 3. View of various unused oil and gas equipment at the pump jack.

Inspection Photos

Location Name: Schumacher 32-6 13-1, 2

Location ID: 334036



Photo 4. Unused metal piping/tubes observed on location.

Inspection Photos
Location Name: Schumacher 32-6 13-1, 2
Location ID: 334036



Photo 5. View of additional unused oil and gas equipment observed at the pump jack.