



99999999

**L & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT**☐ NOTICE OF UNSATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801

Denver, CO 80203

(303)894-2100

☒ NOTICE OF SATISFACTORY INSPECTION

API No. 05- (123 - 05328)

LEASE NAME: Ash #1

LOCATION: SONE-S27-TN-67W

OPERATOR: Chevron USA

DATE: 2/12/98

INSPECTOR: Davelka

Insp. Type: AR

Insp. Status: PA

PA: Y

N

Pass/Fail: P

F

Viol.: Y

N

NOV: Y

N

INSPECTION ITEM**COMMENTS****INPUT**

Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		RECEIVED MAR 5 98 COGCC
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: No surface disturbance found

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00226811

White - File Canary - Operator Pink - Well Site