

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403770309

Date Received:

04/25/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

. General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000603

Inspection Date: 03/22/2024

FIR Submit Date: 03/26/2024

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326347

Location Name: SAULS CREEK GAS UNIT "B"- Number: 27NENW County: \_\_\_\_\_  
N35N6W

Qtrqr: NENW Sec: 27 Twp: 35N Range: 6W Meridian: N

Latitude: 37.276507 Longitude: -107.519099

FACILITY - API Number: 05-067- -00 Facility ID: 326347

Facility Name: SAULS CREEK GAS UNIT "B"- Number: 27NENW  
N35N6W

Qtrqr: NENW Sec: 27 Twp: 35N Range: 6W Meridian: N

Latitude: 37.276507 Longitude: -107.519099

CORRECTIVE ACTIONS:

2 ☒ CA# 193585

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 03/31/2024

Response: CA COMPLETED

Date of Completion: 04/25/2024

Operator  
Comment:

Impacted surface material cleaned up and equipment repaired.

ECMC Decision: Approved pending re-inspection

ECMC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with ECMC standards.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Impacted surface material CA completed. See attached completion photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Gabby Riley

Signed: \_\_\_\_\_

Title: Permitting Specialist I

Date: 4/25/2024 4:42:16 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
403770309	FIR RESOLUTION SUBMITTED
403770318	Sauls Creek B1; CA completion photo - Stain

Total Attach: 2 Files