

Inspection Photos
Location Name: Brown 22-32
API Number: 125-08983



1. Well lease sign at access trail.



2. Well lease sign at well location.

Inspection Photos
Location Name: Brown 22-32
API Number: 125-08983



3. View of wellhead.



4. Flowline mounted gas meter box.

Inspection Photos
Location Name: Brown 22-32
API Number: 125-08983



5. Digital gas meter inside meter box.



6. Electric motor on ground inside well fencing.

Inspection Photos
Location Name: Brown 22-32
API Number: 125-08983



7. Muddy soil at wellhead.



8. Additional view of saturated soil off the front of wellhead outside fencing.

Inspection Photos
Location Name: Brown 22-32
API Number: 125-08983



9. View of wet area outside well fencing.



10. Additional view of wet area outside fencing looking back at well.