

Inspection Photos  
Location Name: Lewis USA 25-15  
Location ID: 322391  
Inspection Date: 4/29/2024

Location sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Lewis USA 25-15  
Location ID: 322391  
Inspection Date: 4/29/2024

Mislabeled tank.



Inspection Photos  
Location Name: Lewis USA 25-15  
Location ID: 322391  
Inspection Date: 4/29/2024

**Mangled wellhead cover and  
landslide within tank battery  
secondary containment structure.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Lewis USA 25-15  
Location ID: 322391  
Inspection Date: 4/29/2024

**Landslide within tank battery  
secondary containment structure.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Lewis USA 25-15  
Location ID: 322391  
Inspection Date: 4/29/2024

**Landslide within tank battery  
secondary containment structure.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources