

Inspection Photos  
Location Name: Haymaker 13C-4HZ  
Location ID: 420156



Photo 1: Tank Battery Signs




Photo 2: Gas meter not calibrated

**Inspection Photos**  
**Location Name: Haymaker 13C-4HZ**  
**Location ID: 420156**



**Photo 3: Weeds removed**



**Photo 4: Weeds removed**



Inspection Photos  
Location Name: Haymaker 13C-4HZ  
Location ID: 420156



Photo 5: Debris




Photo 6: Debris