

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0610-22-43 Pad

Location ID: 324315

Date: 4/24/2024



Location Entrance – Photo #00839



Wellhead – Photo #00844

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0610-22-43 Pad

Location ID: 324315

Date: 4/24/2024



Separator – Photo #00842



Tank Battery – Photo #00840

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0610-22-43 Pad

Location ID: 324315

Date: 4/24/2024



Unprotected Soil Stockpile – Photo #00841



Unprotected Soil Stockpile – Photo #00843

Inspection Photos

Location Name: LARAMIE ENERGY LLC, CC/0610-22-43 Pad

Location ID: 324315

Date: 4/24/2024



Unprotected Soil Stockpile – Photo #00846