

Inspection Photos

04/29/2024

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334558

Inspection Doc: 696205784

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



April 29, 2024



April 29, 2024

Photo 1: Photo 1-2 taken from the south end of the Location, facing northeast and southeast. Photos provides an overview of the Location from west, northwest, northeast to east.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



Photo 2: See comments under photo 1. Photos also examples showing BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation and sediment transport are no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



Photo 3: Photos example showing BMPs to stabilize the working pad surface, as well as to minimize erosion, degradation and sediment transport are no longer in proper functioning condition.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



Photo 4: Photo taken from the location entrance. A thick layer of gravel has been placed at the Location entrance as a "VTC"; aggregate appears to be single sized material- BMP has not been constructed with course multiangular rock of appropriate size; BMP does not appear to be per good engineering practices and is unlikely to be effective during wet or muddy conditions; sediment tracking/transport evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



Photo 5: Liner in disrepair at tank battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



Photo 6: Photos examples showing vegetation establishing around production equipment. This is a potential fire hazard.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



Photo 7: Photo taken from the northeast end of the Location. Photo shows unmarked anchor.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC - 10456

Location ID: 334558



Photo 8: Photos taken from the interim areas on the North end of the Location. Excluding shrubs species, vegetation is predominantly undesirable plant species, including Bulbous bluegrass, purple mustard, etc...