



Inspection Photos  
Location Name: Lewis 36-1  
Location ID: 322396  
Inspection Date: 4/29/2024

Location sign and mislabeled tank.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Lewis 36-1  
Location ID: 322396  
Inspection Date: 4/29/2024

Wellhead sign.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Lewis 36-1  
Location ID: 322396  
Inspection Date: 4/29/2024

Mislabeled PBV.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Location Name: Lewis 36-1  
Location ID: 322396  
Inspection Date: 4/29/2024

Mislabeled PBV.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources