

Final Reclamation and Stormwater Inspection

Date: 4/29/24

Operator: Noble Energy Inc - 100322

Location ID: 447456

Inspection Document #: 713900583

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: Daniels PM K 5-13,K 5-25

Location ID: 447456



Photo 1. The photo was taken at the tank battery location facing North. The photo illustrates the location is dominated by bare soil, Hoary cress and Kochia.

Photo 2. The photo was taken at the tank battery location facing East. Refer to the comment from photo 1.

Inspection Photos

Location Name: Daniels PM K 5-13,K 5-25

Location ID: 447456



Photo 3. The photo was taken at the tank battery location facing South. Refer to the comment from photo 1.

Photo 4. The photo was taken at the tank battery location facing East. Refer to the comment from photo 1.

Note - There is a meter shed and some other piece of equipment still at the location.

Inspection Photos

Location Name: Daniels PM K 5-13,K 5-25

Location ID: 447456



Photo 5. The photo was taken at the tank battery location facing North. The photo illustrates soil staining at the meter shed.