



00204740

WELL SITE INSPECTION FORM

WELL NAME Doll Estate 2 API NUMBER 05 - -
OPERATOR Mark Powell PERMIT NUMBER _____
LOCATION SWNW 14 - 7N - 58W COUNTY Weld
FIELD Raymer INSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____

DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____

TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____

SKIM PIT: _____ gal TANKS: () _____ bbls

EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____

METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____

HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____

MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION 1/20/89

COMMENTS Rods + tbg in hole flowline still hooked up to well

(1) dead mess, dirt mound for p.g. needs to be leveled
upon plugging